HAER MICH Ga-NEWA.V

HAER No. MI-100-B

HISTORIC AMERICAN ENGINEERING RECORD

INDEX TO PHOTOGRAPHS

Hardy Hydroelectric Plant,
Powerhouse
6928 East 36th Street
Newaygo Vicinity
Newaygo County
Michigan

Documentation:

5 exterior photographs (1995)

5 interior photographs (1995)

7 data pages (1997)

Clayton B. Fraser, Photographer, July 1995

For the sake of clarity, sides reflect approximate full cardinal points. Camera angle descriptions are accurate.

- MI-100-B-1 GENERAL VIEW SHOWING DOWNSTREAM (SOUTH) SIDE OF POWERHOUSE, WITH TAILRACE IN FOREGROUND AND EMBANKMENT (MI-100-A) IN BACKGROUND. VIEW TO NORTHEAST.
- MI-100-B-2 DOWNSTREAM (SOUTH) SIDE, WITH TAILRACE IN FOREGROUND. VIEW TO NORTHWEST.
- MI-100-B-3 WEST AND UPSTREAM (NORTH) SIDES WITH SUBSTATION (MI-100-C) AT LEFT. VIEW TO SOUTHEAST.
- MI-I00-B-4 UPSTREAM (NORTH) SIDE WITH SUBSTATION (MI-I00-C) AT LEFT, EMBANKMENT (MI-100-A) IN LEFT FOREGROUND, AND SMOKESTACK IN CENTER FOREGROUND. VIEW TO SOUTH.
- MI-100-B-5 EAST AND UPSTREAM (NORTH) SIDES WITH EMBANKMENT (MI-100-A) IN RIGHT FOREGROUND, SUBSTATION (MI-100-C) AT CENTER, OIL HOUSE (MI-100-F) AT CENTER RIGHT, AND DORMITORY (MI-100-G) AT UPPER RIGHT. VIEW TO WEST.
- MI-100-B-6 INTERIOR VIEW SHOWING THREE GENERATING UNITS
 PROTRUDING THROUGH GENERATOR FLOOR, WITH REPAIR FLOOR
 AT RIGHT. VIEW TO EAST.

HARDY HYDROELECTRIC PLANT, Powerhouse HAER NO. MI-100-B (Page 2)

- MI-100-B-7 INTERIOR VIEW SHOWING REPAIR FLOOR AT LEFT, GENERATING FLOOR MEZZANINE AT CENTER, OFFICE BOOTH AT RIGHT, AND CRANE AT TOP CENTER. VIEW TO NORTHWEST.
- MI-100-B-8 INTERIOR DETAIL OF UPPER THRUST BEARING AND EXCITER FOR GENERATING UNIT #3. VIEW TO NORTHWEST.
- MI-100-B-9 INTERIOR DETAIL OF SWITCHBOARD INSIDE OFFICE BOOTH ON NORTH WALL OF GENERATING FLOOR. VIEW TO EAST.
- MI-100-B-10 INTERIOR DETAIL OF CAST CONCRETE CAPITAL ON BRICK-ENCASED STEEL COLUMN. VIEW TO NORTH.